

OUT61242

P 180150Z FEB 67  
 FM NPIC WASHDC  
 TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB  
 RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAAA/2D RTS BARKSDALE AFB LA  
 RUEPJS/DIA WASHDC  
 RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUCVAAA/2 AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 9906.

1967 FEB 18 02 01Z

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)

2D AF (FOR DI).

1. CAMERA B-15 WAS USED ON [REDACTED]

[REDACTED] PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH  
 SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. DENSITY AND RESOLUTION ARE GOOD.

B. 9R SIDE: MINOR ROLLER CHATTER AND EDGE STATIC ARE PRESENT  
 ON BOTH EDGES THROUGHOUT THE MISSION. NUMEROUS PINHOLES ARE ALSO  
 PRESENT THROUGHOUT THE MISSION. A HEAT SPLICE IS PRESENT IN THE  
 FORMAT OF FRAME 914 AND A MANUFACTURER'S SPLICE IN FRAME 1183.

C. 9L SIDE: ROLLER CHATTER AND EDGE STATIC ARE PRESENT  
 INTERMITTENTLY THROUGHOUT THE MISSION. ALSO MINUS DENSITY DOTS  
 GENERALLY ASSOCIATED WITH ROLLER CHATTER WERE LOCATED ALONG THE  
 INBOARD EDGE. SOME EDGE CRIMPING OCCURRED BETWEEN FRAMES 1191  
 THROUGH 1198.

D. BOTH SIDES: THE LAST TITLED FRAME IS 1864. SMEAR  
 CAUSED BY VEHICLE MANEUVERING WAS RECORDED ON FIVE FRAMES.

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	SEC BR	
	TDS	
	CSO	
	ICD	
	PC	
	POC	
	POC-ICD	
345	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	RSA-LO	
	DIA-AP	

Advance copy  
certified

- 2 -

3. POSITIVE:

- A. THE PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURED APPROXIMATELY 60 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-

1